

The Wand on Lenco L75 v4

(To be read in conjunction with the 'normal' Wand instructions)



We suggest going through a quick 'trial assembly' to understand the process.

1; Remove Lenco arm.



2; Add Wand spindle....



...and add clamping boss underneath.
But do not tighten fully yet.



Note; Tonearm wiring can be fed through into the turntable at this stage but we suggest you don't do this until you understand the setup (easier to lift arm off).

3; Use the protractor to get arm correct distance from spindle (cover Lenco hole) and tighten.




4; Check spindle height is between two marks..... using Hex key to adjust (but very little adjustment possible, only up a few mm)




THE WAND[®]
UNIPIVOT TONEARM

www.thewandtonearm.com
© Dec 2012 design **build** listen Ltd. v4

4a; Extra height can be gained with washers



5. Feed wire thru clip and place arm



6; Check overhang via protractor, may have to loosen screw and move mounting slightly.



7; If using it, adjust Lenco arm lift and arm rest heights.

